



Declaration of Authorization for Service of low voltage motors for explosive atmospheres

Authorized Service Center: FAINARDI & ALBERTINI srl
Via B.Buozzi 10/A
43016 S.PANCRAZIO (PARMA)
Emilia Romagna
Italy

ABB BU Motors and Generators certify that the above Service Center has service engineers trained, workshop facilities and equipment required to perform service on BU Motors and Generators in accordance with the products listed below. The Service Center is qualified and authorized to do repair and service on designated products in accordance with guidance and rules set by ABB.

Related documents: ATEX 95 (94/9/EC), ATEX 137 (1999/92/EC), IEC 60079-14, IEC 60079-17, IEC 60079-19

The Authorized Service Center is authorized to use resources available and have been trained and certified for repair of ABB's motors for explosive atmospheres.

The Authorized Service Center is authorized to carry out overhaul & maintenance meaning replacing damaged parts with original ones of following scope:


Flameproof Ex d, Ex de	IEC 80-450
Increased safety Ex e (cast iron)	IEC 80-400
Increased safety Ex e (aluminum)	IEC 90-280
Non-sparking Ex nA (cast iron)	IEC 71-450
Non-sparking Ex nA (aluminum)	IEC 90-280
Dust ignition Ex t (cast iron)	IEC 71-450
Dust ignition Ex t (aluminum)	IEC 71-280

With this certification is the workshop also authorized to do service on ABB's safe area low voltage motors to the frame size limit as above.

The Authorized Service Center will be responsible for failures related to improper handling/storage and bad workmanship in modifying or repairing the product. Bad workmanship in this context means, rough handling, improper working method, disregard of instructions, carelessness etc. The above mentioned relation can be either direct or indirect.

Certificate number: LVM 390001

Date of issue: December 20th 2011
Authorization to be updated before: September 31st 2014


Marcus Westerlund
Service Network Manager
BU Motors and Generators